

### Exhibit 3: Site Photographs



The upper photo shows the beginning of the trail, heading from the street toward the ocean. The banks of San Vicente Creek are eroding so severely that the bridge in this photo was in danger of collapsing, and had to be replaced in April with a second, slightly longer temporary bridge (pictured on the next page). Erosion continues to threaten the new bridge, and a permanent solution is needed.





### Exhibit 3: Site Photographs



The upper photo shows the new temporary bridge, looking back toward the Fitzgerald Marine Reserve parking lot across the street. This bridge was installed under emergency conditions, and is not designed to be permanent. The lower photo shows the condition of the trail. Improvements are needed to make this trail ADA-compliant.





### Exhibit 3: Site Photographs



The proposed Coastal Trail will be built along existing dirt trails, portions of which need little improvement.



The end of this proposed segment of the Coastal Trail is pictured above, running between the two downed logs and intersecting Cypress Avenue. Hikers can walk around the traffic barrier to access the Bluff Trail, which loops back along the oceanside cliffs to the Fitzgerald Marine Reserve parking lot. Because the cliffs are highly erosive, the Bluff Trail cannot be improved to meet ADA standards. Users with limited mobility can return to the parking lot via the trail on which they came.